

SPA-QUIP

Notice To Customers

Controller Functionality Change

Due to recent changes in electrical safety standards, Spa-Quip controllers now behave differently in the event of a controller error condition. In the past when a controller has entered an error condition it has been possible to reset the controller by turning the power to the controller off then on again.


The controllers are now reset differently, in the event of an error condition the controller can now be reset by pushing a combination of touch pad buttons. The combination of buttons is different depending on the controller model.

Note: Resetting the mains power will not clear an error condition.


The Spa Power 601 controller is the first controller to be changed with all other controllers changing in the near future.

Special note: It is important to match your controller user guide to the controller in the spa, the changes to the reset procedure have been up dated to reflect this, but care will have to be taken not to mix up controllers and user guides. Any SP601 controller received with a serial number above SQG106L339703 will be equipped with this reset method.

To reset the SP601 controller from an error condition simultaneously push the three circled buttons.



2 Rothwell Avenue, North Harbour Industrial Park, Auckland, NZ
www.spa-quip.co.nz



SPA-POWER

SPA EQUIPMENT



N376